Suzanne Steab - April 2011 Inspection Reports

From:

Karl Houskeeper

To:

rnetz@emerytelcom.net

Date:

5/4/2011 3:21 PM

Subject:

April 2011 Inspection Reports

CC:

ANGELANANCE@utah.gov; DARONHADDOCK@utah.gov; SUZANNESTEAB@utah.gov

Attachments: SCA April 2011.pdf; SPWF April 2011.pdf

Rusty,

Attached are the April 2011 inspection reports for SCA and SPWF.

Thanks,

Karl



State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Division of Oil, Gas and Mining

JOHN R. BAZA Division Director

Representatives Present During the Inspe Company Rusty Netz OGM Karl Houskeeper OGM Kevin Lundmark

Inspection Report

Permit Number:	C0070042
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, April 05, 2011
Start Date/Time:	4/5/2011 11:00:00 AM
End Date/Time:	4/5/2011 2:30:00 PM
Last Inspection:	Tuesday, March 15, 2011

Inspector: Karl Houskeeper, Weather: Clear, Temp. 59 Deg. F. InspectionID Report Number: 2704

Types of Operations

Accepted by: jhelfric

4/12/2011

Permitee: SUNNYSIDE COGENERATION ASSOCIATES Operator: SUNNYSIDE COGENERATION ASSOCIATES

Site: STAR POINT REFUSE

Address: PO BOX 159, SUNNYSIDE UT 84539

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current	Acreages
---------	----------

		. Abor or obermous		
152.93 Total Permitted	Federal	Underground		
152.93 Total Disturbed	State	Surface		
Phase I	County	Loadout		
Phase II	✓ Fee	Processing		
Phase III	Other	✓ Reprocessing		

Mineral Ownership

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

all Doushuper Karl Houskeeper.

Tuesday, Ap

Permit Number: C0070042 Inspection Type: PARTIAL

Inspection Date: Tuesday, April 05, 2011

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 For PARTIAL inspections check only the elements evaluated.
 Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
 Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale			[]	
2.	Signs and Markers	V		7	I
3.	Topsoil		[]	O	
4.a	Hydrologic Balance: Diversions	V		Y	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	V			
4.c	Hydrologic Balance: Other Sediment Control Measures		; ====================================		
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations		(***)		["]
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	V		y .	
8.	Noncoal Waste	7			
9.	Protection of Fish, Wildlife and Related Environmental Issues				ij
10.	Slides and Other Damage			, and the second	
11.	Contemporaneous Reclamation			C.J	
12.	Backfilling And Grading		i de la companya de l		1
13.	Revegetation	V	1 1	~	
14.	Subsidence Control			process;	
15.	Cessation of Operations	D			
16.a	Roads: Construction, Maintenance, Surfacing		tona"		(APVII)
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities			13	(J
18.	Support Facilities, Utility Installations				[]
19.	AVS Check		pr =		
20.	Air Quality Permit	<u> </u>		Steen and	inger i
21.	Bonding and Insurance		, his is a		
22.	Other				

Inspection Continuation Sheet

Permit Number: C0070042 Inspection Type: PARTIAL

Inspection Date: Tuesday, April 05, 2011

Page 3 of 3

2. Signs and Markers

The mine identification sign is located on a power pole at the entrance into the permit area. The identification sign contains the required information. Other signs observed during the inspection including boundary markers are in compliance with the regulations.

4.a Hydrologic Balance: Diversions

Tumble weeds have been removed from the culvert inlets and outlets as previously observed on the prior inspection.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile appeared stable. No visible hazards were noted.

13. Revegetation

Observed the area proposed for bond release along the old coarse refuse road. Observations were made in conjunction with drainage controls.